


REVISIONS			
REV	DESCRIPTION	DATE	APPROVED
1	Drawing format change	3/16/03	BVB



**SECTION A - A**

NOTES:

1. 10 SPROCKET HOLE PITCH CUMULATIVE TOLERANCE  $\pm 0.2$
2. CAMBER IN COMPLIANCE WITH EIA 481
3. POCKET POSITION RELATIVE TO SPROCKET HOLE MEASURED AS TRUE POSITION OF POCKET, NOT POCKET HOLE

$A_0 = 28.30$   
 $A_1 = 29.00$   
 $B_0 = 28.30$   
 $B_1 = 29.00$   
 $K_0 = 5.50$   
 $K_1 = 4.20$



TITLE ADVANTEK PART DRAWING NUMBER PFP132-C CARRIER TAPE			
TOLERANCES - UNLESS NOTED 1PL $\pm .2$ 2PL $\pm .10$	MATERIAL PS+C	ALL DIMENSIONS IN MILLIMETERS DWG SIZE B	
DRAWN BY TMD/BVB	DATE 1/25/99	SCALE 2:1	SHEET 1 OF 1
REFERENCE NO. T-8345-A	DWG NO. T101984AT	REV 1	